

KARTA INWENTARYZACJI USZKODZEŃ NAWIERZCHNI

Droga nr: 653 Strona: Prawa Data: 03/10/03

Początek: 23.400

Koniec: 24.900

Hektometr		Pęknięcia siatkowe [m2]		Pęknięcia pojedyncze [m]		Łaty [m2]		Wyboje [szt.]	Ubytki [m2]
		M	D	M	D	M	D		
23.400	- 23.500	0.0	0.0	14.5	24.5	0.0	0.0	0.0	0.0
23.500	- 23.600	42.0	0.0	7.0	8.8	0.0	0.0	0.0	0.0
23.600	- 23.700	92.8	0.0	15.3	7.0	71.8	0.0	0.0	0.0
23.700	- 23.800	22.7	0.0	62.0	0.0	0.0	0.0	0.0	0.0
23.800	- 23.900	70.0	0.0	19.3	0.0	0.0	0.0	0.0	0.0
23.900	- 24.000	0.0	0.0	11.0	0.0	0.0	0.0	0.0	0.0
24.000	- 24.100	29.8	0.0	3.5	0.0	50.7	0.0	0.0	0.0
24.100	- 24.200	10.5	0.0	7.0	0.0	0.0	0.0	0.0	0.0
24.200	- 24.300	22.8	0.0	34.0	22.0	0.0	0.0	0.0	0.0
24.300	- 24.400	0.0	0.0	10.5	0.0	0.0	0.0	0.0	0.0
24.400	- 24.500	105.0	0.0	19.2	5.3	0.0	0.0	0.0	0.0
24.500	- 24.600	175.0	0.0	8.8	0.0	0.0	0.0	0.0	0.0
24.600	- 24.700	124.2	0.0	22.8	0.0	157.5	0.0	0.0	0.0
24.700	- 24.800	0.0	0.0	20.5	0.0	15.8	0.0	0.0	0.0
24.800	- 24.900	0.0	0.0	21.0	0.0	31.5	0.0	0.0	0.0

WIEROBYN K
Pracowni Nawierzchni
Inż. Stawomir Ejsmont